


FUG33 HONDA SERVICE PARTS
PACLI10.044



	PACLITE	Rev. nº 0	
	SPARE PARTS LIST	Date: 11/05/2009	
	HIGH FREQUENCY GENERATOR FUG - 33 HONDA (YELLOW)		PACLI 10.044
QTY.	DENOMINATION	DRAW N°	CODE
1	PLASTIC BOX CONNECTOR	1	PACLI 30.248
3	SWITCH SOCKET 50V 32A	2	PACLI 65.005
1	CHASSIS	3	PACLI 53.502
1	PETROL MOTOR HONDA GX 270 VX (9HP)	4	PACLI 21.003
1	PETROL MOTOR FIXATION SUPPORT	6	PACLI 30.174.1
1	PLASTIC JOINT RUBBER BOX	7	PACLI 76.081
3	SOCKET JOINT	8	PACLI 56.018
1	ASSY STATOR GENERATOR COMP.	9	PACLI 24.075
1	GENERATOR HOUSING	10	PACLI 30.277.1
1	GENERATOR BEARING COVER SEAT	11	PACLI 30.170.1
1	BEARING	12	PACLI 75.045
1	FAN WITH HOSE CLAMP	13	PACLI 33.006
1	BOLT JOINT ROTOR SET	14	PACLI 84.126
1	ROTOR SET (GENERATOR)	15	PACLI 26.053
4	BOLT JOINT M6x172	16	PACLI 84.125
4	SILENBLOC 30x30xM8 (FEMALE-FEMALE)	17	PACLI 56.028
2	SILENBLOC 30x30xM8 (MALE-FEMALE)	18	PACLI 56.031
1	FAN COVER	19	PACLI 48.010
2	BOLT JOINT M6xH40xM8	20	PACLI 84.188